

**Thuroona Services**  
 34 Cocos Drive  
 Bibra Lake  
 WA 6163



**NATA Accredited**  
 Accreditation Number 2377  
 Site Number 2370

Accredited for compliance with ISO/IEC 17025 – Testing  
 NATA is a signatory to the ILAC Mutual Recognition  
 Arrangement for the mutual recognition of the  
 equivalence of testing, medical testing, calibration,  
 inspection, proficiency testing scheme providers and  
 reference materials producers reports and certificates.

**Attention:** Samuel Jackson  
  
**Report** 863006-S  
**Project name** Bridgetown Bushfire Site Investigation  
**Project ID** Connel Road 220213  
**Received Date** Feb 14, 2022

Client Sample ID			Connell 0m Soil	Connell 10m Soil	Connell 200m Soil	Connell 40m Soil
Sample Matrix			L22-Fe24326	L22-Fe24327	L22-Fe24328	L22-Fe24329
Eurofins Sample No.			Feb 13, 2022	Feb 13, 2022	Feb 13, 2022	Feb 13, 2022
Date Sampled						
Test/Reference	LOR	Unit				
Chromium (VI)	1	mg/kg	< 1	< 1	< 1	< 1
Arsenic	5	mg/kg	< 5	< 5	< 5	< 5
Chromium	1	mg/kg	230	190	190	190
Copper	1	mg/kg	10	7.4	6.4	7.3
Lead	1	mg/kg	12	13	12	14
% Moisture	1	%	1.0	1.1	< 1	< 1

Client Sample ID			12 Connell Soil	16 Connell Soil	70 Connell Soil
Sample Matrix			L22-Fe24330	L22-Fe24331	L22-Fe24332
Eurofins Sample No.			Feb 13, 2022	Feb 13, 2022	Feb 13, 2022
Date Sampled					
Test/Reference	LOR	Unit			
Chromium (VI)	1	mg/kg			
Arsenic	5	mg/kg			
Chromium	1	mg/kg			
Copper	1	mg/kg			
Lead	1	mg/kg			
% Moisture	1	%			